

AC SERVO MOTOR Safety Precautions

Thank you for purchasing HIWIN's AC servo motor. Installation and operation of the motor must be in accordance with the HIWIN manual. Before using the servo motor, please read these safety instructions and precautions carefully.

★ Unpacking instructions

1. Before using the servo motor, please read these safety instructions and precautions carefully. HIWIN is not responsible for any damage, accident, or injury caused by incorrect handling.
2. Examine the appearance of the motor for any unusual marks or damage from shipment.
3. Inspect the wires for damage.
4. Do not disassemble the motor. Since the product design has been based on structure calculations, computer simulations, and prototype testing, do not disassemble the product without the permission of HIWIN engineers.
5. Supervise children when handling this product.
6. People with psychosomatic illness or insufficient experience should not handle this product, unless under the direct supervision of managers or product narrators.

If any items are damaged or incorrect, please contact your distributor or HIWIN sales representative.

★ Safety instructions

1. The product can only be repaired by HIWIN engineers. Please send the product back to us if there is any unusual phenomenon.
2. Do not hold the motor by its wire harness or shaft.
3. Do not hit the motor or shaft. Shock can damage the encoder inside the motor.
4. Do not apply loads to the motor shaft that are in excess of the specified value.
5. Protect the motor and encoder from high electrical noise, vibration, and unusual temperatures.
6. Do not change the motor parts or disassemble the screws. HIWIN will not be responsible for any damages, injuries, or accidents that may occur.

★ Wiring instructions

1. Ensure the specified power input value before using the product, and verify that the proper power supply is being used.
2. Before operation, please ensure that the motor, brake, and encoder are connected correctly. Incorrect wiring may cause abnormal motor operation or even cause permanent damage to the motor.
3. To avoid voltage coupling and electrical noise on the encoder, ensure adequate separation of the motor power wires and the encoder wires.
4. Ensure that the motor ground wire is connected to the ground terminal on the servo drive.
5. Do not perform a dielectric voltage-withstand test on any encoder terminal. The test may cause damage to the encoder.

★ Operation instructions

1. Higher than maximum specified current may cause demagnetization of magnetic components inside the motor.
2. The AC servo motor is designed to operate through a dedicated servo drive. Do not connect to a commercial power source (100/200V AC, 50/60 HZ). The motor will not operate correctly and may cause permanent damage.
3. The motor must be operated within its specified range.

4. Attention should be given to ensure adequate cooling and ventilation of the motor during operation.
5. For long term use, the motor shaft should be resupplied with proper and sufficient oil during the period of operation.
6. If any abnormal odor, noise, smoke, temperature rise or vibration is detected, stop the motor immediately. Remove power from the servo drive and isolated the motor.

★ Maintenance and Storage instructions

1. Do not store the product in an inflammable environment or that with chemical agents.
2. Store the product in a place without humidity, dust, harmful gases, or liquids.
3. The motor shaft opening is neither waterproof nor oil-proof. Do not install the motor in an environment where there is harmful gas, liquid, excessive moisture, or water vapor.
4. Do not store the servo motor where it will be subjected to vibration or shock in excess of the specified limit.
5. The storage and transportation temperature of this product: $-10^{\circ}\text{C}\sim+50^{\circ}\text{C}$
6. Clean : Wipe with Alcohol (70%)
7. Before shipping, the motor shaft is coated with antirust oil to protect the motor shaft against rust formation. However, the material of the motor shaft is not entirely rust-proof. When the motor storage time has exceeded six months, please inspect and examine the motor shaft and resupply with proper and sufficient antirust oil at least once every three months thereafter.
8. Product abandoned : Follow the local laws and regulations for recycling.

A one year guarantee is provided from the date of delivery. For product damage caused by improper operation (Please refer to the notes and instructions in this operation manual). HIWIN will not be held responsible for replacing or maintaining the product as a result of any natural disasters that may occur during this period.



Warning : For the proper use of the HIWIN AC servo motor read these safety precautions carefully before installation, operation, and maintenance.

Caution : Please read these safety precautions before using the product.

Caution : Do not alter the instrument without the permission of the manufacturer.

Caution : Remove the broken power line buckle carefully.

Caution : The product cannot be used in an inflammable environment.

Caution : Remove the power before cleaning.


Caution : Overload use of this product will cause the temperature of the cover to rise.

Rotary Motor

1. AC Servo Motor	1
Servo Motor Series.....	1
Servo Motor Features	1
Servo Motor 100W Model	3
Servo Motor 200W Model	4
Servo Motor 400W Model	5
Servo Motor 750W Model	6
Motor Power Cable.....	7
Encoder cable.....	7
AC Servo Motor and Driver Wiring	8
2. mega-fabs Israel Driver	9
AC Servo Accessories	13
3. Two Line Stepping Motor	14
Stepping Motor Series.....	14
Stepping Motor Features Curve.....	14
40mm Stepping angle 1.8° ST40 Model.....	15
55mm Stepping angle 1.8° ST55 Model.....	16
4. Stepping Driver (STD-24A)	17
Base Specifications	17
Wiring and Set-up	17
The connect with PCI-4P Wiring Example	19
The connect with PLC Wiring Example.....	19
Connect Figure	20
Shape Figure	20
Stepping Motor Accessories	20
5. Motor assembly hold for HIWIN Single Axis Robot	21
6. DC Brush Motor	22
DC Brush Motor Series	22
Motor Features Curve	22
Position Inspect Function.....	23
Motor Use Information	23
AM1 Model.....	24
AM3 Model.....	26
AM4 Model.....	27
AM6 Model.....	28
AM7 Model.....	30
7. Rotary Motor Requirements List	31





1. AC Servo Motor




AC Servo Motor Ordering Information




AC Servo Motor Features

- Output Power [W] : The power of motor is working at continuous torque and speed.
- Nominal Torque [Tc] : Motor is working at nominal current.
- Nominal speed [ω_c] : Motor is working at nominal output power.
- Peak Max. Torque [Tp] : It is 2~3 multiple of continuous torque.
- No Load Max. speed [ω_p] : Motor is working at no Load.
- Peak Max. current [Ip] : It is 2~3 multiple of continuous current.






AC Servo Motor 100W Model




	Symbol	Unit	FRAC□□1011□□	FRAC□□1022□□
Input Voltage	V	V	AC110	AC220
Output Power	W	W		100
Nominal Torque	T _c	N.m		0.32
Peak Max. Torque	T _p	N.m		0.96
Nominal Current	I _c	A(rms)		0.9
Peak Max. Current	I _p	A(rms)		2.7
Nominal Speed	ω _c	rpm		3000
No Load Max. Speed	ω _p	rpm	4000	4500
Torque Constant	K _t	N-m / Arms		0.356
Back EMF constant	K _e	Vrms / krpm		21.98
Resistance (line to line)	R	Ω		8.23
Inductance (line to line)	L	mH		14.17
Number of poles	P	-		8
Inertia of rotating Parts	J	kg·m ²		0.036*10 ⁻⁴
Weight	M	kg		0.6
Encoder Resolution	CPR	pulse		2500
Brake Keep Torque	T _b	N-m		0.32
Brake Voltage	V	V		DC24±10%
Case shelter grade			IP65	
Insulation grade			H-grade	
Environment	Work temperature		0°C~40°C	
	Preserve temperature		-15°C~70°C	
	Work Humidity		80%RH down	
	Preserve Humidity		80%RH down	
	Preserve Environment		Indoor & keep off causticity air, easy Ran air, oil and dirty.	
	Elevation		1000m down	
Vibrate		49m/s ² down		

AC Servo Motor 200W Model




	Symbol	Unit	FRAC□□2011□□	FRAC□□2022□□
Input Voltage	V	V	AC110	AC220
Output Power	W	W		200
Nominal Torque	Tc	N.m		0.65
Nominal Current	Ic	A(rms)	3.2	2
Peak Max. Torque	Tp	N.m		1.95
Peak Max. Current	Ip	A(rms)	9.6	6
Nominal Speed	ω	rpm		3000
No Load Max. Speed	ω_p	rpm	4000	4500
Torque Constant	Kt	N-m / Arms	0.2	0.325
Back EMF constant	Ke	Vrms / krpm	12.275	19.64
Resistance (line to line)	R	Ω	1.04	2.756
Inductance (line to line)	L	mH	2.86	7.52
Number of poles	P	-	8	8
Inertia of rotating Parts	J	kg-m ²		0.26*10 ⁻⁴
Weight	M	kg		0.86
Encoder Resolution	CPR	pulse		2500
Brake Keep Torque	Tb	N-m		1.3
Brake Voltage	V	V		DC24±10%
Case shelter grade			IP65	
Insulation grade			H-grade	
Environment	Work temperature		0°C~40°C	
	Preserve temperature		-15°C~70°C	
	Work Humidity		80%RH down	
	Preserve Humidity		80%RH down	
	Preserve Environment		Indoor & keep off causticity air, easy Ran air, oil and dirty.	
	Elevation		1000m down	
Vibrate		49m/s ² down		

AC Servo Motor 400W Model



	Symbol	Unit	FRAC□□4011□□	FRAC□□4022□□
Input Voltage	V	V	AC110	AC220
Output Power	W	W		400
Nominal Torque	Tc	N.m		1.3
Nominal Current	Ic	A(rms)	3.2	2
Peak Max. Torque	Tp	N.m		3.9
Peak Max. Current	Ip	A(rms)	9.6	6
Nominal Speed	ω	rpm		3000
No Load Max. Speed	ω_p	rpm	4000	4500
Torque Constant	Kt	N-m / Arms	0.4	0.65
Back EMF constant	Ke	Vrms / krpm	24.17	37.96
Resistance (line to line)	R	Ω	1.79	4.634
Inductance (line to line)	L	mH	5.3	13.92
Number of poles	P	-	8	8
Inertia of rotating Parts	J	kg-m ²		0.44*10 ⁻⁴
Weight	M	kg		1.48
Encoder Resolution	CPR	pulse		2500
Brake Keep Torque	Tb	N-m		1.3
Brake Voltage	V	V		DC24±10%
Case shelter grade			IP65	
Insulation grade			H-grade	
Environment	Work temperature		0°C~40°C	
	Preserve temperature		-15°C~70°C	
	Work Humidity		80%RH down	
	Preserve Humidity		80%RH down	
	Preserve Environment		Indoor & keep off causticity air, easy Ran air, oil and dirty.	
	Elevation		1000m down	
Vibrate		49m/s ² down		


AC Servo Motor 750W Model




	Symbol	Unit	FRAC□□7522□□
Input Voltage	V	V	AC220
Output Power	W	W	750
Nominal Torque	T _c	N.m	2.4
Nominal Current	I _c	A(rms)	5.1
Peak Max. Torque	T _p	N.m	7.2
Peak Max. Current	I _p	A(rms)	15.3
Nominal Speed	ω	rpm	3000
No Load Max. Speed	ω _p	rpm	4500
Torque Constant	K _t	N-m / Arms	0.47
Back EMF constant	K _e	V _{rms} / krpm	28.4
Resistance (line to line)	R	Ω	0.813
Inductance (line to line)	L	mH	6.59
Number of poles	P	-	8
Inertia of rotating Parts	J	kg-m ²	1.4*10 ⁻⁴
Weight	M	kg	2.66
Encoder Resolution	CPR	pulse	2500
Brake Keep Torque	T _b	N-m	2.4
Brake Voltage	V	V	DC24±10%
Case shelter grade		IP65	
Insulation grade		H-grade	
Environment	Work temperature	0°C~40°C	
	Preserve temperature	-15°C~70°C	
	Work Humidity	80%RH down	
	Preserve Humidity	80%RH down	
	Preserve Environment	Indoor & keep off causticity air, easy Ran air, oil and dirty.	
	Elevation	1000m down	
Vibrate	49m/s ² down		

Motor Cable

Single	Color	AMP-4PIN(M)
U	Red	3
V	White	2
W	Black	1
GND	Green	4



Connect pins position definition




Encoder Cable

Encoder Specifications

- A/B/I phase output, RS-422 Line Driver output
- Inspect motor poles position of U,V,W phase Signal
- 2500 resolution
- Work temperature for -200C~+850C.
- 200KHz frequency response
- Work voltage DC +5V±5%
- RoHS


Connect pins position definition



Increase Encoder

Function	Single	Color	AMP-9PIN(M)
Power	5V±5%	Red	1
	0V	Black	2
Increase	A +	Blue	3
	A -	Blue/Black	4
	B +	Green	5
	B -	Green/Black	6
Ref.	Z +	Yellow	7
	Z -	Yellow/Black	8
Shielding	Shielding	Black	9

AC Servo Motor and Driver Wiring



Number	Name	Description
1	AC power input	To single-phase, three-phase AC power
2	Motor power connect	To input power for Motor
3	REGEN Resistor connect	To REGEN resistor for Motor
4	Logic power /Brake	DC 24V of logic power and brake output
5	RS 232 connect	To PC
6	Control single connect	To Controller
7	Feedback single connect	To Motor encoder

2. mega-fabs Israel Driver

Application for AC Servo Motor \ Linear Motor
Instruct Control Model


- Position, Speed, Torque

Input Type

- $\pm 10V$ analogy instruct (Position /Speed/Torque)
- PWM instruct (Speed/Torque)
- Pulse model has electronic gear function
- I/O Digital signal



Drive Series




Application industry

- Faceplate Industry
- Semiconductor equipment
- PCB.AOI equipment
- Automation Industry


Specifications

Item	Driver		Specifications
	Item	Value	
Max pulse command bandwidth	Pulse Input	2M Pulse/s max.	
	Quad A/B	8M Count/s max.	
Encoder Signal	Digital	5V \pm 5% RS422	
	Analog	1Vp-p (Sin/Cos)	
DC power input (Control loop power)	24VDC \pm 10% / 1A		
AC power output (Motor drive power)	100~240VAC/ 1 & 3 Phase		
Digital input point	10 inputs(5Vdc)		
Digital output point (Open Drain)	3 outputs(24VDC)		
Dynamic brake output signal	DC 24V / 0.5A max.		
Weight	1,250 g		
Work temperature	0 $^{\circ}$ C ~ 45 $^{\circ}$ C		
Store temperature	-20 $^{\circ}$ C~ +85 $^{\circ}$ C		

Driver Size



Driver Interface



Wiring

● MAIN POWER

Signal	PIN
Main Input L3	L3
Protective Ground	⊕
Main Input L2	L2
Main Input L1	L1

● MOTOR OUTPUTS

Signal	PIN
Phase U	U
Phase V	V
Phase W	W
Cable Shield	⊕

● REGEN RESISTOR

Signal	PIN
Frame GND	⊕
No Connect	NC
REGEN Resistor (-)	REG-
No Connect	NC
REGEN Resistor(+)	REG+

● CN1 RS232

Signal	PIN
No Connect	6
TxD_MAIN	5
Signal GND	4
Signal GND	3
RxD_MAIN	2
No Connect	1

● +24VDC & BRAKE

Signal	PIN
24V+	24V+
Brake Signal	BRK
24V+ Return	RTN

● CN2 CONTROL SIGNALS

Signal	PIN	Signal	PIN	Signal	PIN
Frame GND	1	P+/A+/CW+ [I9]	10	/B	19
Signal GND	2	D+/B+/CCW+ [I10]	11	Z	20
ENABLE [I1]	3	[I11]	12	/Z	21
[I2]	4	ALM [O1]	13	+5VE	22
[I3]	5	INPOSITION [O2]	14	Signal GND	23
POS LIMIT [N4]	6	[O3]	15	REF+	24
NEG LIMIT [I6]	7	A	16	REF-	25
P-/A-/CW- [I7]	8	/A	17	[I12]	26
D-/B-/CCW- [I8]	9	B	18		

● CN3 MOTOR FEEDBACKS

Signal	PIN	Signal	PIN	Signal	PIN
Frame GND	1	Z	8	Signal GND	15
Signal GND	2	/Z	9	SIN(+)	16
+5VDC	3	Signal GND	10	SIN(-)	17
A	4	HALL A	11	COS(+)	18
/A	5	HALL B	12	COS(-)	19
B	6	HALL C	13	Signal GND	20
/B	7	Motor Over Temp.	14		

● STATE

LED Color	State
RED	ERROR
GREEN	Servo Ready

Software

Name : Lightning

Apply : WINDOWS Series

Computer equipment :

- CPU:586 MHz over
- RAM:128 MB over
- RS-232 serial port or USB port with a USB to RS-232 adapter.

Software obtain information :

- CD Rom for produce
- <http://www.hiwinmikro.com.tw>

Driver Accessories

Name	Number	Description
Accessories	051800200057	24Vdc connect x1 MAIN POWER connect x1 MOTOR OUTPUTS connect x1 REGEN connect x1 MOTOR FEEDBACK connect (case) x1 Connect Toolx2

Driver Accessories

Name	Type	Connect	Description
Ⓐ RS-232 Cable	LMACR21D	CN1	
Ⓑ AC Servo Motor Power Cable	HV04FRACP□□A HV04FRACP□□B (flexible)	MOTOR OUTPUTS	
Ⓒ AC Servo Motor Power Cable (Brake)	HV06FRACP□□A HV06FRACP□□B (flexible)	MOTOR OUTPUTS	
Ⓓ AC Servo Motor Encoder Cable	HV00FRACE□□A HV00FRACE□□B (flexible)	CN3	

List A

□□	30	50	70	A0
L (m)	3	5	7	10

Connect pins position

HV04FRACP□□A
HV04FRACP□□B

Signal	AMP 4Pin	Western-style post
U	3	U
V	2	V
W	1	W
≡	4	≡

HV06FRACP□□A
HV06FRACP□□B

Signal	AMP 6Pin	Western-style post
U	3	U
V	2	V
W	1	W
≡	4	≡
B+	5	B+
B-	6	B-

HV00FRACE□□A
HV00FRACE□□B


Signal	AMP 9PIN	SCSI 20Pin (Male)
5V	1	3
0V	2	2
A+	3	4
A-	4	5
B+	5	6
B-	6	7
Z+	7	8
Z-	8	9
Shading	9	1,20

3. Two Phase Stepping Motor

Stepping Motor Ordering Information


		FR	ST	0	20	0	24	01	
Product	Model	Phase/Shaft		Type	Step Angle		Voltage	Serial number	
Motor	ST:	0: 2S (2phase/single)		1X: ST42	0: F (stepping angle 1.8 meh.)		24V	01~99	
	Stepping Motor	1: 2D (2phase/double)		2X: ST55	1: H (stepping angle 0.9 meh.)				

Characteristic Curves of Stepping Motor




- Pull-in Torque**
 It is the Max. torque that stepping motor and input signal are starting, stop synchronously. The range under of pull-in torque that motor can starting, stop synchronously and forward/reverse. The range is Starting rang oneself.
- Max Pull-in Torque**
 It is the starting pulse frequency lower than 10 pps, the Max torque of stepping motor can input signal for starting, stop synchronously.
- Max Pull-in Frequency**
 It is the Max input pulse rate of motor at no load that motor can stop, start in instant.
- Max Pull-in Torque**
 It is the motor and input signal for work synchronously, but can't start ,stop in instant for Max torque. The torque larger than output torque that motor be not work. The output torque below and start torque above of region in the meantime, the motor can't start or stop in instant that region is call slew region. It must be relay start region oneself at start and stop in slew region, otherwise has out of set.
- Max Response Frequency**
 The output torque is equal zero for Max input frequency in motor at no load that calls it. In instant the Motor can't start or stop at the moment.
- Holding Torque**
 It is exerting max torque for extra add load to change rotor position in rotor keep motionless that motor stator winding is enable.

40mm Step Angle 1.8° ST40 Series




Model	Winding Type	Holding Torque	Current	Resistance	Inductance	Rotor Inertia	Leads	Motor Length	Input Voltage
Single axis		N.m	A/phase	Ω/phase	mH/phase	g-cm ²		(L)mm	Vdc
FRST01102401	Single Pole	0.1	0.95	4.2	3.0	19	6	47	4

● Wiring Diagram





- Notice:
- ★ Please use the wire which is larger than 0.5mm² and as short as possible for power and motor connection.
 - ★ Support 2 phase stepping motor (6 lead wire).

55mm Step Angle 1.8° ST55 Series



Model		Winding Type	Holding torque N.m	Current A/phase	Resistance Ω/phase	Inductance mH/phase	Rotor Inertia g·m ²	Leads	Motor Length (L)mm	Input Voltage Vdc
Single axis	Double axis									
FRST02102401	FRST12102401	Single Pole	0.25	1.3	2.3	2.9	90	6	50.5	3
FRST02202401	FRST12202401	Single Pole	0.6	1.3	3.1	4.8	171	6	65	4
FRST02302401	FRST12302401	Single Pole	1.05	1.2	4.4	7.8	290	6	87	5.3

● Wiring Diagram



Notice:
 ★ Please use the wire which is larger than 0.5mm² and as short as possible for power and motor connection.
 ★ Support 2 phase stepping motor (6 lead wire).

4. HIWIN Stepping Driver (STD-24A)

Specification

- 2 phase stepping motor (6 lead wire)
- Signal Pole current driver
- Micro-stepping driver function
- Constant output current 0.2A~2A
- Max Frequency response 150000Hz
- Support Pulse/Direction Pulse (1P)
- Support CW/CCW Pulse (2P)
- Support Quadrature Pulse (A/B)
- Additional Positive/Negative pole limit control
- Motor exciting release
- RoHS certificate
- CE safe characteristic



Connect and Setting


1. LED State

- LED display

Display	Color	function
LED1	Red	Power light
LED2	Green	State light

- State light Information



Drive State	LED State
Forward	low speed flash (0.5s/per)
Reverse	high speed flash (0.2s/per)
Limit Input	low speed flash (1s/per)
Exciting release	dark
Stand by	light



2. Input / Output


Interface	Pin	Input / Output	Mark
(CN1)	1	Power Input	DC24V
	2		Power Input
	3	Motor connect	COM A
	4	Motor connect	COM B
	5	Motor connect	A +
	6	Motor connect	A -
	7	Motor connect	B +
	8	Motor connect	B -
	9	Pulse single Input	CW +
	10	Pulse single Input	CW -
	11	Pulse single Input	CCW +
	12	Pulse single Input	CCW -
	13	Control single	MF
	14	Control single	LSF
	15	Control single	LSR
	16	No use	NC

● Input Pulse Single Wiring Diagram




- Notice:
- ※ Please use the wire which is larger than 0.5mm² and as short as possible for power and motor connection.
 - ※ Pulse width please corresponds to the sketch.
 - ※ These signal types are accepted by driver :


A. Pulse/Direction (1P)




B. CW/CCW (2P)



C. Quadrature (A/B)




● Limit Input \ Motor Disable Wiring Diagram



- Notice:
- ※ The function was triggered by closing the switch [ON].
 - ※ The forward limit signal is ON , motor will not rotate even receiving forward pulse command. Furthermore, The reverse limit signal is ON , motor will not rotate even receiving reverse pulse command.
 - ※ Motor release signal is ON, exciting release.


HIWIN PCI-4P Wiring Example



PLC Wiring Example




Connect Diagram



Notice:
 ※ Please input DC+5V pulse.
 ※ Please use twisted line or shading line as signal line which is as short as possible.

Size Diagram



Stepping Motor Accessories

Name	Type	Connect	Description	Stepping Motor Cable Wiring Table		
Stepping Motor Cable HV00FRSTP□□A MOTOR OUTPUTS				Signal	6Pin [F]	Western-style post
				COM A	1	COM A
				A-	2	A-
				A+	3	A+
				COM B	4	COM B
				B-	5	B-
B+	6	B+				

List A


□□	30	50	70	A0
L (m)	3	5	7	10

5. HIWIN Robot and Motor Adaptor Flange


Motor Flange List

Model	AC 100W	AC 200W	AC 400W	AC 750W	ST40-21	ST55-21	ST55-22	ST55-23
KK40	F2	-	-	-	F3	F3	F3	F3
KK50	F2	-	-	-	F3	F3	F3	F3
KK60	F2	-	-	-	F5	F5	F5	F5
KK86	-	F0	F0	-	-	-	-	-
KK100	-	F0	F0	F1	-	-	-	-
KK130	-	F1	F1	F2	-	-	-	-
KA100	F1	-	-	-	-	-	-	-
KA136	-	F0	F0	-	-	-	-	-
KA170	-	F0	F0	F1	-	-	-	-
KS05	FE	-	-	-	-	-	-	-
KS10	Inner Type	-	-	-	-	-	-	-
KS14	-	Inner Type	Inner Type	-	-	-	-	-
KS18	-	Inner Type	Inner Type	-	-	-	-	-

Robot connect Stepping Motor



Robot connect Servo Motor



6. DC Brush Motor

Ordering Information

Product	Model	Accessory	Type	Voltage	Serial number
Motor	01 : Brush DC Motor 02 : Stepping Motor	0 : only motor 1 : motor + gear 2 : motor + encoder 3 : motor + gear + encoder	01 : AM1 03 : AM3 06 : AM6 07 : AM7	012 : 12V 024 : 24V MAX : 100V	01-99

Illustration for Characteristic Curves of Motor

According to the customer use for meeting the main value of the motor load moment demand specifications, corresponds to the characteristic curve in the rotational speed (ns), the electric current (I), the power (P) and so on, can obtain the final operation range. Like the chart shows, when customers choose motor operation and the load moment is A, may obtain the coordinates position B, C, D respectively be the rotational speed, electric current and power value.

For example:
Torque position A requirement is : 2.8N.m
By position C to obtain speed is : 2200rpm
At this time corresponds to position B \ D respectively be the current and power value is 9A and 63W.





Illustration for Capability of Encoder



※The principle of picking out the Hall IC

The voltage input range of Hall IC is about 2.4V~26V. The Hall IC will create the induced voltage signal (See Fig 1) through the NS magnetic field of circular magnet. (See Fig 2). The NS poles of circular magnet will decide the signal frequency which is interrelated to the numbers of magnet pole and the rotational speed of motor. As shows on Fig 1, there are 8 poles of circular magnet to induce on one piece Hall IC. When the magnet operates one cycle, the output will obtain the voltages between Uh~-Uh from Hall IC. The 5 points (a, b, c, d, a) are located respectively in the measure positions from the circular magnet of Hall IC. The motor rotation circumference can be divided into 8 equal portions and obtains pulse signal precisely, as shows on Fig 2.

Cautions

1. Please avoid any mechanical interference when motor operates. Otherwise it will break down the motor.
2. Please follow the voltage specification to input DC voltage. Then the DC voltage can be able to provide with the current under maximum loading which named "Duty maximum current".
3. When switch the +/- power supply, the motor will operate reverse movement.
4. Please don't exceed the standardized motor maximum loading.
5. Please follow the waterproof specification use.

